








	БПЗ-1211 $F \text{ см}^2 = 1.120$ $Q \text{ кг.} = 0.304$ $D \text{ оп.мм} = 33.7$ $P \text{ н.мм} = 90.0$ $P \text{ вн.мм} = 81.3$ Гр. сл. = V Точн. = П		БПЗ-1216 $F \text{ см}^2 = 4.724$ $Q \text{ кг.} = 1.280$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 259.9$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = 0соб.
	БПЗ-1212 $F \text{ см}^2 = 0.730$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 72.9$ $P \text{ вн.мм} = 63.0$ Гр. сл. = V Точн. = П		БПЗ-1217 $F \text{ см}^2 = 13.766$ $Q \text{ кг.} = 3.731$ $D \text{ оп.мм} = 103.0$ $P \text{ н.мм} = 340.2$ $P \text{ вн.мм} = 289.0$ Гр. сл. = V Точн. = Н
	БПЗ-1213 $F \text{ см}^2 = 2.248$ $Q \text{ кг.} = 0.609$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 147.6$ $P \text{ вн.мм} = 58.0$ Гр. сл. = V Точн. = Н		БПЗ-1218 $F \text{ см}^2 = 7.903$ $Q \text{ кг.} = 2.142$ $D \text{ оп.мм} = 140.0$ $P \text{ н.мм} = 348.3$ $P \text{ вн.мм} = 387.5$ Гр. сл. = VI Точн. = П
	БПЗ-1214 $F \text{ см}^2 = 27.200$ $Q \text{ кг.} = 7.371$ $D \text{ оп.мм} = 133.0$ $P \text{ н.мм} = 442.9$ $P \text{ вн.мм} = 72.0$ Гр. сл. = V Точн. = Н		БПЗ-1219 $F \text{ см}^2 = 9.704$ $Q \text{ кг.} = 2.630$ $D \text{ оп.мм} = 115.0$ $P \text{ н.мм} = 367.0$ $P \text{ вн.мм} = 271.8$ Гр. сл. = 0соб. Точн. = П
	БПЗ-1215 $F \text{ см}^2 = 1.610$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 129.2$ $P \text{ вн.мм} = 120.3$ Гр. сл. = VI Точн. = П		БПЗ-1220 $F \text{ см}^2 = 5.683$ $Q \text{ кг.} = 1.540$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 291.7$ $P \text{ вн.мм} = 201.3$ Гр. сл. = V Точн. = П