









			БПЗ-1336 $F \text{ см}^2 = 14.800$ $Q \text{ кг.} = 4.011$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 550.5$ $P \text{ вн.мм} = 388.8$ Гр. сл. = 0соб. Точн. = П
	БПЗ-1332 $F \text{ см}^2 = 6.787$ $Q \text{ кг.} = 1.839$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 229.9$ $P \text{ вн.мм} = 147.8$ Гр. сл. = VI Точн. = П		БПЗ-1337 $F \text{ см}^2 = 2.540$ $Q \text{ кг.} = 0.688$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 183.5$ $P \text{ вн.мм} = 174.1$ Гр. сл. = IV Точн. = П
	БПЗ-1333 $F \text{ см}^2 = 2.083$ $Q \text{ кг.} = 0.564$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 100.8$ $P \text{ вн.мм} = 54.0$ Гр. сл. = V Точн. = П		БПЗ-1338 $F \text{ см}^2 = 9.896$ $Q \text{ кг.} = 2.682$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 163.4$ $P \text{ вн.мм} = 119.4$ Гр. сл. = III Точн. = П
	БПЗ-1334 $F \text{ см}^2 = 5.502$ $Q \text{ кг.} = 1.491$ $D \text{ оп.мм} = 99.0$ $P \text{ н.мм} = 479.9$ $P \text{ вн.мм} = 0.0$ Гр. сл. = VI Точн. = П		БПЗ-1339 $F \text{ см}^2 = 3.181$ $Q \text{ кг.} = 0.862$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 84.8$ $P \text{ вн.мм} = 56.6$ Гр. сл. = III Точн. = П
	БПЗ-1335 $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 176.8$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = П		